

PERFORMA FOR THE SAFETY OF SCHOOL BUILDING


(To be filled by the Head of School Institute)

1. Name of the school : BHARTIYA VIDYA MANDIR HIGH SCHOOL
2. Location : URBAN ESTATE PH-III DUGRI,LDH.
3. Plot Area : 3100 SQ. YRD.
4. Plinth Area :11160 SQ. FT. (Total Area 41010 SFT)
5. Number of Storey :BASEMENT,GROUND FLOOR,I FLOOR, II FLOOR
6. Year of construction of building :2002-2003
7. Supervision of then qualified engineers :

The following details may be given

- a) Name of Engineer :HARISH SAGGAR & ASSOCIATES
  - b) Address : BINDRABAN ROAD, CIVIL LINES,LDH.
  - c) Set of structure drawing used in construction  
If available
  - d) Name of Architect : HARISH SAGGAR & ASSOCIATES
8. Whether the building has been construction for the purpose of
- a) School :  Yes/ No
  - b) Residential purpose and converted for use as a school :  Yes/ No
9. Materials used for Roof
- a) RCC Slabs :  Yes/ No
  - b) P.S. Joints and Battons :  Yes/ No
10. Wooden Joints and Battons
- a) Mud Motor :  Yes/ No
  - b) Cement Motor :  Yes/ No
  - c) Plaster :  Yes/ No
  - i) Lime Moraor :  Yes/ No
  - ii) Cement Mortar :  Yes/ No
11. Flooring
- a) Congoimerate :  Yes/ No
  - b) Teraazzo :  Yes/ No
  - c) Brick paving/Marble Flooring :  Yes/ No

12. Detailed drawing indicating dimension of the Rooms along with size and location of doors and Windows.



  
Principal  
Bhartiya Vidya Mandir Sr. Sec. School  
Urban Estate Ph-III, Dugri, Ludhiana  
Affiliation/D No. 4556 (P.S.E.B.)



Part-II


To be filled by S.D.E. of P.W.D.B & R Department

- a. I have visited the above mentioned school on 06/04/23 and have visually inspected it from all angles of safety and I find it fit for normal use of building.
- b. In case, any additional alteration or expansion and modification to the building is to be carried out under the supervision of a technically qualified Engineer and this certificate may again be obtained after the completion from the undersigned.
- c. In case the building is affected by flood or if there is a settlement of walls found them caving of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.
- d. This building can be safe by occupied for normal use up to 31/03/2024  
(indicate year upto which I can be used.)

  
ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ  
ਉਸਾਰੀ ਮੰਡਲ ਨੰ: 3  
ਲ.ਨਿ.ਵਿ.ਭ ਫੋ ਮ ਸ਼ਾਖਾ,  
ਲੁਧਿਆਣਾ।  
  
SE

ਪਿੱਠ ਅੰਕਣ ਨੰ. 03-04 ਮਿਤੀ. 06-04-23

1. ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ PRINCIPAL, BHARTIYA VIDYA MANDIR SENIOR SECONDARY SCHOOL URBAN ESTATE PH-III, DUGRI, LUDHIANA ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਅਗਲੇਰੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।
2. ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ.1, ਲੇ.ਨਿ.ਵਿ., ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਲੁਧਿਆਣਾ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਅਗਲੇਰੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

  
ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ  
ਉਸਾਰੀ ਮੰਡਲ ਨੰ: 3  
ਲ.ਨਿ.ਵਿ.ਭ ਫੋ ਮ ਸ਼ਾਖਾ,  
ਲੁਧਿਆਣਾ।  
